Page 1 of 12 Pages						
CCR No. 98-0	082 Logged D	Date 1/22/98	Rev	Request Ty	/pe CCR	
Priority Routine	X	Emergency	Affected Release	В	Change Class INS	
Title (description) Upgrade IBM 3590 tape drive microcode						
Documents Affected Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or						
Hardware baseline COT'S VERSION BASE NO.						
	910-1D	A-0036	1			
RTM Change	Start New Base	eline 🗌				
Problem						
The IBM 3590 microcode will not work with AMASS 4.9.X						
Proposed Solution	***************************************					
•	ocode level I9_430 at L	andover, GSFC (AML/	2 and AML/E), EDC a	nd LaRC		
Release notes attached.						
	,					
Noed Da	ite: 1/26/9	G 0				
Impact Analysis:	16. //20//	/ 8				
Organizations Affected:	воо 🔲	Contracts [ECS Chief Eng	FOS	M&O X	
Procurement	∞ □	Rel. Dev	Rel. A	Rel. C	SCDO Arch.	
Science Off	Security	Subcontret	Sys. Eng X	Sys Verf Acpt		
Cost:	None X	Small (Not exceeding \$100,000)	Medium	Large (Over \$500,000)		
Schedule:	None X	(Not exceeding \$100,000) Other	:\$100,000 to \$300,000,	(OVB: #JUU.GUC,		
Additional LOC						
Materials						
		-3.	Toma		04/00/00	
Originator Byron V. P	'eters	Signature UE	TO TO THE PARTY OF		01/22/98 Date	
	0" N	Q (100) a	in M	J/as	198	
Office SENHWE	Office Manager	Signature	liker	.,	Date	
Disposition	Approved 📈	Approved w/Comr	nent Forw	vard	Disapproved	
Comments:	, pp. 11	, , , , , , , , , , , , , , , , , , , 				
Comments.		_	\sim			
		- 16		1	1	
	CCB Chairperson	Twfi	ikes	1/2	3/98	
		Signature			Date	

CM010C96

OPIGINAL

c/m tra